



SERVICE BULLETIN

SB No. 005

Issue No. 1 Aircraft Type T67A

TITLE

Inspection of Mainplane Walkways

CLASSIFICATION Recommended

COMPLIANCE Inspection to be carried out within 50 flying hours of receiving this Bulletin.

APPLICABILITY: All Slingsby T67A Aircraft.

JUSTIFICATION:

A recent inspection of a T67A aircraft revealed knife cut damage where the wing walk tape had been trimmed. This is a potential area for water ingress.

ACTION:

Inspect the edge of the wing walkways for damage.

If knife cuts are apparent and penetrate into the wood, report findings to Slingsby Aviation.

MAN HOURS:

1/2 hour inspection.

ISSUED BY:

B. Meller

Date 10.2.83

for and on behalf of **SLINGSBY ENGINEERING LIMITED**
Kirkbymoorside, York YO6 6EZ, England. Tel. 0751 31751 Telex 57911

Page 1 of 1