**SERVICE BULLETIN**

SB No. 025

Issue No. 2

**TITLE**

FLIGHT IN THUNDERSTORM AND LIGHTNING ACTIVITY

**CLASSIFICATION**

This S.B. is classified as Mandatory by the U.K. C.A.A.

**COMPLIANCE**

From receipt of this bulletin.

APPLICABILITY

All T67 GRP Series aircraft with Mod 272B or Mod 177B fitted.

ACTION

As a result of revised lightning strike requirements the following limitation now applies:

When Mod 272B or 177B is fitted the aircraft must not be flown in the vicinity of known or forecast thunderstorm or lightning activity.

NOTE:


Retrospective incorporation of modification Mod M366A deletes Temporary Amendment Leaflet TAL/1 from Flight Manual. Equally deletes Mod M272B (stbd elevator only) from log book.

Incorporation of Mod M366C deletes Mod M272B in its entirety. For Mod Bulletin and further information contact SAL Product Support Department.

**ISSUED**

19 NOV 1989

ISSUED BY:



Date

8<sup>th</sup> Nov 89.

for and on behalf of

SLINGSBY AVIATION PLC

Kirkbymoorside York YO6 6EZ England Tel 0751 32474 Telex 57597

Page

1

of 1