**SERVICE BULLETIN**

SB No.

78

Issue No.

2

TITLE

INSPECTION OF RUDDER CABLES AND THEIR FAIRLEAD PULLEYS

CLASSIFICATION

Recommended

COMPLIANCE Within one month of date on this Bulletin or at next 50 hr inspection, then at all routine annual inspections or 500 hrs whichever comes first.

APPLICABILITY: T67C & T67M-MkII Aircraft (Post Mods M419 & M456), T67M260 & T67M260-T3A

WITH REFERENCE TO ISSUE 1:

Under ACTION, Item No. 6:


RHP Pt No. "FL6418" should read "FL6419".

Enc. Issue 1, if required.

ISSUED

30 JUN 1995

ISSUED BY:



for and on behalf of SLINGSBY AVIATION LIMITED

Kirkbymoorside York YO6 6EZ England Tel 0751 32474 Telex 57597

Date 30.6.95

Page 1 of 1