



SERVICE BULLETIN

SB No.

108

Issue No.

1

TITLE
MAINTENANCE OF OIL CROSSOVER VALVE FOR CORRECT OPERATION
CLASSIFICATION

This Service Bulletin has been classified by SAL as Recommended

COMPLIANCE

This S.B. issued for information only

APPLICABILITY:

T67M, T67M-MkII, T67M200, T67M260 and T67M260-T3A.

INTRODUCTION:

This Service Bulletin is issued to draw to the attention of operators/maintenance organisations of the requirement to flush the oil system as noted in the Lycoming Operators Manual.

ACTION

1. Ensure systems are cleaned - in accordance with Lycoming Operators Manual Section 3 Cleaning Inverted Oil System - at every 300 hours.
2. Upon re/fitting new/existing oil crossover valve, check valve for correct operation in accordance with Lycoming Operators Manual Section 3 - Maintenance.

ISSUED BY:


Date 19-12-96

for and on behalf of

SLINGSBY AVIATION LIMITED
 Kirkbymoorside, York YO6 6EZ, England.

 Tel. 01751 432474
 Fax 01751 431173

Page 1 of 1