**SERVICE BULLETIN**

SB No.

135

Issue No.

1

TITLE

HOFFMANN SERVICE BULLETIN/LETTER LISTING

CLASSIFICATION

This Service Bulletin has been classified by SAL as Essential

COMPLIANCE

As requested by each Hoffmann Service Bulletin/Letter Unless Otherwise Specified.

APPLICABILITY:

T67M260 and T67M260-T3A.

INTRODUCTION:

This Service Bulletin is issued to list all Hoffmann Service Bulletins/Letters relating to the Hoffmann Propeller HO-V123K-KV/180DT ITP as used on the Slingsby T67M260 and T67M260-T3A Firefly.

This Service Bulletin will be updated periodically to add further Hoffmann Service Bulletins/Letters when received.

ACTION:


Operators are to ensure they have a complete set of the relevant Hoffmann Service Bulletins/Letters, as per attached list, and that they have complied with them.

For copies of Hoffmann Service Bulletins/Letters listed, please contact Hoffmann.

ATTACHMENTS:

Hoffmann Service Bulletins/Letters List Issue 1 (1 page)

ISSUED BY:



Date

27 Aug 97

for and on behalf of

SLINGSBY AVIATION LIMITED
Kirkbymoorside, York YO6 6EZ, England.Tel. 01751 432474
Fax 01751 431173

Page

1

of 1

SB/SL No	Subject	Applicable to USAF	Comment
E1 (S)	Propeller TBO	Yes	
E2	Inspection of Safety Device Low Pitch Stop	Yes	Complied with In Build
E3	Replacement of Pitch Change Fork	Yes	Complied with In Build
E4(C)	Blade Root Retension (HOV62)	No	
5	HO-V113 Propeller	No	
E6	Cracks in Suction Side of Blade HO-V123()-()/180R	No	
E7	Hoffmann Blades Fitted to Dowty Roto! Propellers	No	
E8(REV2)	Adjustment of Blade and Counterweight Angle	Yes	
	Note all comments made against Pt No HO-V123K-KV/180DT		